



# Pump Alignment



**PUMP**  
(Fixed Machine - FM)

**MOTOR**  
(Movable Machine-MM)





# MACHINERY ALIGNMENT

- **Table of Contents**

- (a) What is Alignment
- (b) What is Misalignment
- (c) Types of Misalignment
- (d) Method of Alignment
- (e) Symptoms of Misalignment
- (f) Pre Alignment Checks
- (g) Tools Required For Alignment
- (h) Alignment Tolerances

# What is Machinery/Shaft Alignment?

- The center lines of rotating shafts form a single line when the machines are working at normal operating temperature .
- Arrangement in a straight line .



# Aligning Your Machinery Mean...

- 1. Performance and protection of industrial equipment.**
- 2. Increase operating time.**
- 3. Increase production**
- 4. Cost saving**

# What is Misalignment & Types


- Shaft misalignment occurs when the center lines of coupled shafts do not match up.

There are two Types of misalignment.

1) Offset/**Radial** Misalignment


2) Angular /**Axial** Misalignment

More than 50% problems are due to misalignment .



# Radial Misalignment

- Parallel (radial) misalignment occurs when the driving and driven shafts are parallel but with some offset between their axial centers.
- Radial Misalignment can be further classified as
  - 1) **Radial Vertical Misalignment**
  - 2) **Radial Horizontal Misalignment**




# Axial Misalignment

➤ Angular misalignment occurs when the axial centers line of driving and driven shafts intersect.


Axial Misalignment can also be classified as

- 1) Axial Vertical Misalignment
- 2) Axial Horizontal Misalignment
- 3) Combination



# Axial Misalignment


UNDERSTANDING AXIAL  
AXIAL - AT 180



MEANS THERE ARE MORE SHIMS AT #2 AND LESS #1 \*REMOVE SHIMS AT #2



# *Misaligned Your Machinery Mean..*

- 1. Is a risk to your business.*
- 2. Lead to unplanned*
- 3. production stops.*
- 4. Consume more power.*
- 5. Can affect the quality of*
- 6. the product you are*
- 7. manufacturing.*
- 8. Financial loss.*



# Types of Misalignment

- 1) Parallel Displacement or Radial Displacement
- 2) Face Displacement or Angular Displacement
- 3) Combination



# Method of Alignment

- Rough Alignment

1=Straight Edge ,steel rule, feeler gauge & Wire Method

## Precision Alignment

2 = Rim & Face Method

3 = Reverse Method/Graphical Method




4 = Laser Method

# Method of Alignment


- **feeler gauge and steel rule:** This method is used when the coupling are mostly flexible and there is no spacer in between both hubs.
- Axial alignment check by feeler gauge.
- Radial alignment check by knife edge rule .



# ALIGNMENT




# BY STRAIGHT EDGE







# Alignment with straight edge

Alignment of V belt , pulleys, sprockets and gears.



# Method of Alignment

## Shaft Alignment



# Symptoms of Misalignment

1. Premature bearing, seal, shaft and coupling failure
2. High vibration
3. High Casing / Bearings / Oil Temperatures
4. Excessive oil leakage from bearing seals
5. Coupling is hot
6. Foundation bolts get loosen
7. Coupling bolts/Shims broken or loosen
8. Shafts are breaking (or cracking) at or close to the inboard bearings or coupling hubs Similar machine has less vibration

# Effects of Misalignment

Misalignment can cause the following problems on the running machine. Vibration in the machine and associated / linked equipment's.

A.Excessive wear and temperature rise in the bearings.

B.It causes coupling failure.

C.Abnormal noise arises

D.Over loading of prime movers

E.Decreases the efficiency of the machine

# Causes of Misalignment

- 1) Thermal Expansion
- 2) Stress.
- 3) Soft foot.
- 4) Bearing Failure.
- 5) Vibration.
- 6) Poor workmanship.

# Mechanical Causes of Vibration

- 1) Unbalanced rotating components. Damaged impellers
- 2) Misalignment
- 3) Pipe strain.
- 4) Either by design or as a result of thermal growth.
- 5) Thermal growth of various components, especially shafts.
- 6) Rubbing parts.
- 7) Worn or loose bearings.
- 8) Loose hold down bolts.
- 9) Loose parts.

# Why Precise Alignment is needed?

- 1) ■ These factors increases the need of precise alignment and balancing to minimize vibration and premature wears of couplings, bearings and shaft seals.
- 2) ■ Stresses from misalignment are directly proportional to the speed of unit.

# Alignment States

## Cold Alignment

Alignment which is carried out when the machine is at cold state.

## Hot Alignment

- Alignment which is carried out when the machine is at hot state.

# Pre-Alignment requirements?

## Foundation

- Grout
- Base plate
- Piping
- Coupling Installation
- Soft Foot
- Shims
- Sag
- Feeler gauge

# Foundation


- Thumb Rule

- Concrete weight should be equal to three times machine weight for rotating machines
- Concrete weight should be five times for reciprocating machines



# Grout

- Should be in good condition
- Tapping with a small hammer can detect hollow spots



# Base Plate

- Should be rigid
- Machine mounting pads should be level flat and clean.



# Piping

- Well fitted and supported.
  - Stress Free.
  - Sufficiently flexible, no more than 0.08mm
- vertical and horizontal movement occurs at coupling



# Coupling

The coupling should be installed with a light interference fit with shaft.

Vary from .002” to .005” per inch of the shaft diameter.



# Soft Foot

- **Machine feet do not rest flatly on the base of machine.**

One or more feet of a machine differ in height from the others .




- Soft foot is caused by deformed machine base plates or deformed machine feet.
- This method is commonly used for soft foot check & correction.
- Place the Dial at foot of machine.

Tighten all hold down bolts then loosen one bolt at a time and note the deflection






**Maximum soft foot allowable limit is 0.05mm**

# Soft Foot

- Soft foot must be detected and eliminated on both the driving and driven machines before performing the alignment. Soft foot should be checked in each stages of the alignment . **1=pre-alignment 2=Final alignment.** Soft foot check by feeler gauge and dial indicator .



# SOFT FOOT



# Shims

- The shims used should be large enough to adequately support each foot.
  - Don't use Dirty shims-Clean them
  - Many shims replace with fewer thick shims
  - Use Pre-cut stainless steel shims
  - Don't reuse painted, or badly bent shims
  - Best choice for shim material is stainless steel
  - Maximum shim limit is 12mm
  - Try to use max 5 or less shims under each foot.
- Its not always possible but try to minimize

# SAG

**The Inclination towards downwards in alignment Bracket due to gravitational force is called Bracket Sag .**

Sag does not normally effect horizontal alignment.


But in vertical measurement it depends on the spacer length

Q For less then 6” length of the spacer sag is negligible.

Q For spans greater then 6” sag should checked & Note down.

# SAG CHECK

Dial



# Thermal Growth

- For liquids 93 C° and below set motor shaft at same height as pump shaft.
- For liquids above 93 C°, set pump shaft lower or motor shaft higher as per OEM Recommendation.
- For foot mounted pumps or turbines



# Tools required for Machinery alignment



- 1) Dial Indicator (two dials)
- 2) Two brackets (for reverse indicator method)
- 3) Straight Edge/Steel Rule,
- 4) Meter tape
- 5) Venire Caliper
- 6) Micro meter
- 7) Inspection Mirror
- 8) Crowbar
- 9) Tool Box
- 10) Shims

# Alignment Methods (Cont.)

- **Alignment with Straight edge/Feeler Gauge.**
  1. Allowed only on flexible coupling, as precise alignment can not be achieved.
  2. Radial misalignment is checked / corrected with the help of straight edge or knife edge.
  3. Axial misalignment is checked / corrected with the help of feeler gauge & ID Mic.
  4. This method is used only for aligning the shafts of non critical machines.

# MACHINERY ALIGNMENT

- Pulleys /Sprockets Alignment With Steel Rule/Straight Edge
- V Belt pulleys or sprockets can be align with straight edge bars/Steel Rule or strings.



# Graphical or Reverse method


- In this method two dial indicators are fixed on both hub rims(radially).
- The dials are fixed on both sides such driver and driven. Shim calculate on graph paper .

One set of readings is taken from the loose machine to the fixed machine, and the second set of readings is taken from the fixed machine to the loose machine.

- It is therefore sometimes referred as reverse method.
- These readings are then plotted on the graph using suitable scale. How

- .


# Graphical or Reverse method



# Laser Method

1. The most modern & accurate method for aligning the shafts.
2. Laser alignment is the process of determining
3. misalignment by a laser beam.
4. Where laser is mounted on one shafts and a receiver or reflector is mounted on the other.
5. Both shafts are turned at the same time. The
6. deviation in the laser beam is measured as the shaft is turned and readings show on Display Unit.

# Laser Method




# Rim & Face Method

For using dial indicators, it is necessary to prepare a suitable Fixture, which can hold two or three dial indicators

One dial indicators (R), with the axis in the radial direction, will measure the radial misalignment of the shafts. And one dial indicator (A) with the axis in the axial direction, will measure the axial misalignment of the shafts.

# Rim & Face Method

Rim Measurement




Face Measurement

# Dial Indicator


- ✓ Dial indicator can be used when there is a spacer between both hubs .
- ✓ One dial is fixed on the face of the hub ,for axial alignment and other is fixed at the rim of the hub ,for radial alignment
- ✓ Dial on fixed moveable machine .
- ✓ View from fixed machine.
- ✓ Dials must be some pre load for reading .
- ✓ After zero.
- ✓ When the dial indicator main pointer rotates by  $360^\circ$ , the dial indicator small pointer will show 1mm displacement of the rod

# Dial Indicator



# Rim & Face Method

- Place the dial on the rim & Face of the coupling hub and secure it with the help of suitable Fixture.
- Measure the data during a rotation of  $360^\circ$ . The algebraic sum of the values read on the horizontal plane ( $90^\circ$  &  $270^\circ$ ) will be equal to the values read on the vertical plane ( $0^\circ$  and  $180^\circ$ ).



# Advantages & Disadvantages of Rim & Face Method

## Advantages:

Good for large dia coupling hubs where the shafts are close together.

To be used where one of the shafts can not rotate during alignment.

Easy to use.

## Disadvantages:




Difficult to take face readings, if there is axial float in the shaft

Requires removal of coupling spool.

Indicator Sag


# SPIDER COUPLING GAPE

- After alignment spider must be free inside of the jaws.
- Maintain the gap between the jaws ,2mm-4mm .




# Tightening Hold Down Bolts

- Bolts should always be tightened in a known sequence so that vertical positions are repeated as you re-tighten the bolts.




# Coupling Gap

- An improper coupling gap causes excessive axial forces which result in increased bearing load.
- Improper gap can also cause destruction of an electric motor with plain bearings.
- The coupling gap should be set to the manufacturer's specification (to take care of thermal expansion in axial direction). **DBSE= Distance between shaft end**  
**DBFF= Distance between face to face**



# Setting the Coupling Gap

- ✓ You check the coupling gap with a scale, feeler gauge, taper gauge, or an inside micrometer.
- ✓ Move the motor axially to set the proper gap.
- ✓ Electric motors with plain bearings have endplay.
- ✓ Therefore, you must position the motor shaft at magnetic center before setting the coupling gap.



# Important Tips

1. Clean the Machine Base, Removes Rust, burrs etc.
2. Perform pre-alignment checks on machine
3. Use correct bolt tightening procedure.
4. Use jack bolts
5. Try to put the stem of dial gauge perpendicular to the surface of coupling hub
6. Check indicator sag
7. Check Run out of(Bent shaft, Out of round couplings)
8. Check the coupling gap

# Important Tips

- After decoupling the machine, take alignment reading, if time permits. It serves as a reference reading, as some time it becomes difficult to get the desired readings.
- Before alignment, always ensure that there is no “soft footing” in the machine. If it exists, remove it prior to align.
- Use Jacking Bolts For move the Motor Never use Hammer
- If the machine has more than four feet, then it is better to carry out the alignment of the machine by reverse /graphical method.
- Always carry out the alignment job in the early day time.